



The polarity of the input power supply can be either plus or minus. The polarity of all the commons, however, must match.

The COM terminals are internally connected, but they all must be wired.