


PLC I/O Unit	<b>CS1W-ID231</b>
Connector Terminal Conversion Unit	<b>XW2D-40G6</b>
Connecting Cable	<b>XW2Z-□□□B</b>

Connections Diagrams



Dotted lines are used in the above diagram to indicate input power supplies that can be connected with either polarity. Use the same polarities, however, for the commons in rows A and B respectively. Although there are 2 pins each for COM0 and COM1, which are connected internally, wire to all the pins.