


Connections for SYSMAC CS1-series I/O Units

PLC I/O Unit	CS1W-ID261
Connector Terminal Conversion Unit	XW2D-40G6
Connecting Cable	XW2Z-□□□B



Connections Diagrams

Dotted lines are used in the above diagram to indicate input power supplies that can be connected with either polarity. Use the same polarities, however, for the commons in rows A and B respectively. Although there are 2 pins each for COM0, COM1, COM2, and COM3, which are connected internally, wire to all the pins.