


For M Series Use


XW2Z-□□□J-B2



Connector

Servo Driver side

Servo Terminal
Unit side



MR-50LF
(Honda Tsushin Kogyo)

XG4M-2030-T

Wiring Diagram

R88D-MT□□
(Multi-pole square
connector with 50 poles)

XW2B-□□J6-□B
(XG4M-2030)

