


PLC I/O Unit	CS1W-OD232
Connector Terminal Conversion Unit	XW2D-40G6
Connecting Cable	XW2Z-□□□B



Although the COM(+V) and 0V terminals in rows A and B are respectively connected internally, wire to all the terminals.